



QUALITECH ENVIRONMENTAL SERVICES LIMITED

Distribution Centre Flooding

A solid orange horizontal bar at the bottom of the slide.

Incident support



Qualitech received an emergency call because a distribution centre loading bays and parking area was flooding.

This was causing a health and safety risk to the drivers and an environmental risk to the site.

The site was at risk of closure.

Qualitech responded with a mobile pump and fuel bowser to start to clear the standing water.

This was supported by Qualitech staff late into the night and then again in the early morning.

Incident Summary



This is the loading bays with the standing water cleared.

Qualitech continued to support the pump down whilst the problem with the drains was investigated.

The site has since resolved the problem.



Thank you for your time.

Presented by Qualitech