



QUALITECH ENVIRONMENTAL SERVICES LIMITED

Manufacturing Plant Fire

A solid orange horizontal bar spanning the width of the slide at the bottom.

Incident support



Qualitech were called out to assist in the decontamination and cleaning operation after a fire at a manufacturing plant.

The fire caused total devastation to the plant which can be seen on the left.

The cleaning involved using high vacuum DISAB trucks to suck up the debris for disposal.

Incident Summary



There was packaged material to be made safe for transport and disposal after the event.

The responders made safe the site using booms to control the fire water and assisted in the command and control of the incident.

Rainfall also was a factor and added to the complications of dealing with the cleanup operations.

After the event



The area had to be fully decontaminated to ensure the safety of the environment and to allow the site to take stock of the situation and make plans for moving forward.

The site has since returned to full production.



Thank you for your time.

Presented by Qualitech